FITNESS REPORT

Name of the Institution St.LUIGI English Medium School

Mariyathuruthu P O, Thiruvatta, Kottayam

Classification of Building Three storied RCC Framed Structure

Six Classrooms 6mx6mx3.6m + Computer room

6mx6.3mx3.6m in Second floor.

Area of Second Floor 530.37 Sqm (35.2x9.2x3.6m, 19.15x9.2x3.5m &

6.5x6.5x3.6m)

Year of Construction

2023-24

Observations

1. Nature of defects, if any

a)	Foundation	and	basement	 NIL
100				

- b) Superstructure NIL
- c) Doors and Windows NIL.
- d) Woodwork wrought and put up NIL
- e) Roof NIL
- f) Flooring NIL.
 g) Miscellaneous NIL
- 2. No major defects were noticed that will render the building unsafe.
- 3. The structure is sound for the intended function under normal weather conditions.

CERTIFICATE

Certified that the second floor of the above building was inspected by me on 17/05/2024 and found to be fit to function as a school building for the period 2024-2025.

Place: Ettumanoor Date: 27/05/2024

SEOF THE ASSISTANT EXE. ENGINEER

AND THE ASSISTANT EXE. ENGINEER

SEOF THE ASSISTANT EXE. ENGINEER

AND THE ASSISTANT EXE

Assistant Executive Engineer

JIPSON JOSE
Assistant Executive Engineer
LID & EW Sub Division
Ettumanoor Block Panchayat
PEN: 613982